MSA 711, MSA 811

MSA 711

MSA 811

Dimensions, mounting tolerances MSA 711:



Dimensions, mounting tolerances MSA 811:



measuring length (ML)	n
ML > 56 - 600	2
ML > 600 - 1200	4
ML > 1200 - 1800	6
ML > 1800 - 2400	8
ML > 2400 - 3000	10
ML > 3000 - 3040	12

M = machine guideway
ML = measuring length
◁—▷ = 0 ... ML
A = cable

LHI12 = male connector

K = required mating dimensions

FX = fixed mounting
FL = flexible mounting

OPTIONAL:
S1, S2 = switch signals
RI = selectable reference mark

* = actuator magnet
** = sensor position